
| City of Baltimore Wet<br>Smoke and Dyed   | Page 1 of 1                           |  |
|---|---------------------------------------|--|
| Sewershed: Gwynns Falls                   | Date: 9/9/2009                        |  |
| Test to be performed:  Smoke Dyed Water X | Ground Condition:  Dry ✓ Damp □ Wet □ | Supervisor: JAW                              |
| Manhole_ID: S02CC1007MH                   | Test ID: <u>D1032-027009</u>          | Notification Made: NA (Residents, Fire, 311) |

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



| Defect Loc  | Obs_ClockFrom | Obs_ClockTo | Observation      | Obs_Remarks          |
|-------------|---------------|-------------|------------------|----------------------|
| 0           |               |             | Manhole          | S02CC1007MH          |
| 0           |               |             | Start of Survey  |                      |
| 0           |               |             | Water Level      |                      |
| 4           |               |             | Dye Test Visible | DYE SEEN AT JOINT    |
| 7           |               |             | Dye Test Visible | DYE SEEN AT JOINT    |
| 10.89999962 |               |             | Dye Test Visible | DYE SEEN AT JOINT    |
| 14          |               |             | Dye Test Visible | DYE SEEN AT JOINT    |
| 25.20000076 |               |             | Abandoned Survey | DYE TEST IS COMPLETE |